

montageanleitung „shining image“

- die leuchte im ausgangszustand




fig.1

- kleben sie die mitgelieferten gummifüÙe auf die unterseite der bodenplatte. (die seite mit dem aufkleber)
 - fädeln sie das kabel in den schlitz der grundplatte ein




fig.2

- führen sie die befestigungsschraube durch die bodenplatte in das gelenk.




fig.3

- ziehen sie die schraube fest an. nehmen sie ggfs. einen schraubenschlüssel zur hilfe. drehen sie hierbei auf keinen fall am gelenk selber. zum entgültigen festziehen kann das gelenk um höchstens ein halbe umdrehung gedreht werden.



fig.4

assembly instructions "shining image"

- the lamp in initial state

- fix the enclosed rubber feet at the bottom of the ground plate. (the side with the sticker)
 - insert the cable into the slot of the ground plate.

-introduce the mounting screw through the ground plate into the hinge.

- tighten the screw using a spanner, if necessary. do not rotate the hinge itself! finally the hinge can be turned for a half rotation.

montage des motifs:

schrauben sie den halter an das motiv. (abb. 7-8)
dehen sie die madenschraube mit dem beiliegenden
inbusschlüssel aus dem leuchtenkopf. stecken sie
den halter in den leuchtenkopf ud schrauben sie
ihn mit der madenschraube fest.

**achten sie darauf, dass das leuchtmittel gerade in
der fassung sitzt und nicht mit der blende des fas-
sungshalters in berührung kommt.**

die leuchte ist ausgelegt für eine netzspannung von
230 v.

wenn sie eine beschädigung an den zuleitungen
oder am trafo bemerken, trennen sie die leuchte
sofort vom stromnetz!

durch den in die anschlussleitung integrierten dim-
mer kann die leuchtstärke der leuchte stufenlos
eingestellt werden.

die leuchte besitzt einen elektronischen dimmer,
der auch zum ein- und ausschalten dient.
zum einschalten der leuchte berühren sie kurz den
carbonstab. nochmaliges kurzes berühren schaltet
die leuchte aus. wenn sie den carbonstab länger
berühren verstellt sich die helligkeit der leuchte
stufenlos.

pflgehinweise:

reinigen sie ihre leuchte mit einem trockenen tuch.
falls nötig kann für den fuss und das carbonrohr
ein leicht feuchtes tuch verwendet werden.
ölen sie die kugel des gelenkes nicht ein.

sonstige hinweise:

sollten sie für ihre leuchte ersatzteile wie z.b.
leuchtmittel benötigen, wenden sie sich bitte an
ihren händler.

wechselln des leuchtmittels:

trennen sie die leuchte vom stromnetz.
leuchtmittel 12 v 50 w max. sockel g6,35 nieder-
druck matt. achten sie auf dieses zeichen:



lassen sie die leuchte abkühlen! der leuchtenkopf
kann sehr heiß werden. **verbrennungsgefahr!**
ziehen sie das defekte leuchtmittel aus der fassung
heraus und ersetzen sie es durch ein neues. s. ver-
meiden sie dabei das leuchtmittel mit bloßen fin-
gern zu berühren.




fig.7




fig.8

the assembly of the motif:

screw the fastener on the .(abb. 7-8)
take out the grub screw with the enclosed l-shaped
hexagon key from the light head. put the fastener
into the light head and screw tightly with the grub
screw. **please be sure and also control the position
of the bulb in the socket. the bulb must be straight
in the bulbholder. it is very important that the
black faceplate has no contact with the bulb.**

the lamp is designed for a 230v line voltage.
if you note damages at the wiring or the transfor-
mer, immediatly separate the lamp from the power
supply!

thanks to the dimmer, which is integrated into the
wiring of the lamp, the luminous intensity is infini-
tely variable.

the lamp has an electronic dimmer which can also
be used for turning on and off.
for turning the lamp on, quickly touch the carbon
bar. another quick touch will turn the lamp off.
if you touch the carbon bar for a longer while, then
the luminous intensity of the lamp will be infinite-
ly variable.

maintenance instructions:

clean the lamp with a dry cloth. if necessary, a
slightly moist cloth can be used for cleaning the
foot and the carbon pipe. do not grease the ball of
the hinge.

other instructions:

if you need spare parts for your lamp like illumi-
nants, please contact your dealer.

changing the illuminant:

separate the lamp from the power supply.
illuminant 12v 50 w max. base g 6,35 low pressure
matt. pay attention to this symbol:



allow the lamp to cool down! the lamp head can
become very hot. **danger of burning!**
remove the defect illuminant from the socket and
replace it with a new one. avoid touching the illu-
minant with the bare fingers.